


CAUTION


Some older model radios have interference issue near the following camera models: **VisioLogix M1G3**



Radio_Interference_APX1000.mov

The model radios reported with screeching noise when making a call about 5 inches from the camera

| | |
|---|---|
|  | Model: Motorola XTS1500 |
| | RECOMMENDATION |
| | Avoid using near camera. Suggest to use over the ear camera with the M1G3. Customers have successfully used the radio with the M1G3 camera on their belt while wearing the over the ear camera. |

| | |
|---|---|
|  | Model: Motorola APX1000 |
| | RECOMMENDATION |
| | Avoid using near camera. Suggest to use over the ear camera with the M1G3. Customers have successfully used the radio with the M1G3 camera on their belt while wearing the over the ear camera. |